

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Year surveyed \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

By \_\_\_\_\_

Subsequent Corner Restoration

Species *cedar* \_\_\_\_\_  
Diameter *6"* \_\_\_\_\_  
Bearing *S 31 E* \_\_\_\_\_  
Distance *1945* \_\_\_\_\_

Bearing Trees

Year surveyed *1876*  
Original monument *lost*

Original Government Survey

EXISTING SURVEYS

Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
Corner common to sections *33, 34*

CASS COUNTY LAND CORNER RECORD

Index No. *X 13*

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

*Certificate - Jim Parker - 1985*  
*set 2 1/2" 1/2" w/ brass cap - stamped - set lost*  
*10" Birch S 35 E 5.60'*  
*10" Birch S 39 W 6.97'*  
*Doc. # 281983*

Bearing Trees, Reference Objects

Evidence of Subsequent Corner Restoration

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_


Original Bearing Trees Found

Monument found \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_

Original Evidence Found

O = Corner



Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_