


Index No. 613

CASS COUNTY LAND CORNER RECORD

T. 144 R. 26 M. 5TH Coordinates: X _____ Y _____
E14 9 Corner common to sections 9, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Tam Stub
Diameter _____
Bearing N30W
Distance 50 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1971 By William Okerman
Location filed _____
Monument Set 2" x 1/2" galvanized steel pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>
Diameter	<u>8"</u>	<u>8"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>S87W</u>	<u>S73E</u>	<u>S29E</u>	<u>S39W</u>
Distance	<u>35.20'</u>	<u>70.70'</u>	<u>82.20'</u>	<u>50.30'</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1971 - FILED IN 1979
DOC. # 258561

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____