


Index No. R17

CASS COUNTY LAND CORNER RECORD

T. 144 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 27 Corner common to sections 22, 23, 26, 27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>
Diameter	<u>3"</u>	<u>4"</u>	<u>3"</u>
Bearing	<u>N10W</u>	<u>N3W</u>	<u>N46E</u>
Distance	<u>37LKS</u>	<u>39LKS</u>	<u>122LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By JAMES FLYNN  
Location filed COUNTY BOOK 'C' P. 179  
Monument FIND OLD GOVT B.T. 5708 4" TAM N3W  
39LKS AND STUMP 3" TAM N46E 122LKS. SET  
8" x 30" TILING PIPE

Evidence of Subsequent Corner Restoration

Year of search 1959 By DNR-Engineering  
Map notes in file  
Found 6" Dia clay tile pipe w/ wood  
post in center

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_