Index No. V23

# CASS COUNTY LAND CORNER RECORD

T. 144 R. 26 M. 5TH Coordinates: X _____ Y _____

N1/4 36 Corner common to sections 25, 36




## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1873

Original monument Post

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | Aspen | Tam | | |
| Diameter | 14" | 8" | | |
| Bearing | N7E | S10E | | |
| Distance | 57 LKS | 11 LKS | | |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1919 By JAMES FLYNN

Location filed COUNTY BOOK C P. 175

Monument NEW BITS (BELOW)

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | ASPEN | SPRUCE | | |
| Diameter | 7" | 10" | | |
| Bearing | S | N41 W | | |
| Distance | 24' | 44' | | |

### Bearing Trees, Reference Objects

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____