


T. 144 R. 27 M. 5th Coordinates: X _____ Y _____
NE 11 Corner common to sections 12, 14, 12



EXISTING SURVEYS

Original Government Survey
Year surveyed 1873
Original monument post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Species	Bearing	Tree	Distance
<u>Poplar</u>	<u>J. line</u>	<u>Poplar</u>	<u>J. line</u>
<u>6"</u>	<u>6"</u>	<u>6"</u>	<u>4"</u>
<u>S60W</u>	<u>N71W</u>	<u>N35E</u>	<u>S4E</u>
<u>27LKS</u>	<u>44LKS</u>	<u>38LKS</u>	<u>18LKS</u>

Species	Bearing	Tree	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
Year surveyed 1937 By GLO
Location filed Sec. of State
Monument Find NE & NW BTS - now 16 1/4" and Stumps
of SE & SW Set concrete post w/ brass cap 7 1/4" x 1 1/4"
(6" Dia 2' long)

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

Species	Bearing	Tree	Distance
<u>W. Pine</u>	<u>W. Pine</u>	<u>N. Pine</u>	<u>Spruce</u>
<u>7"</u>	<u>6"</u>	<u>5"</u>	<u>6"</u>
<u>N49E</u>	<u>S51 1/4 E</u>	<u>S63 1/2 W</u>	<u>N46W</u>
<u>73LKS</u>	<u>46LKS</u>	<u>52LKS</u>	<u>37LKS</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1972 - FILED IN 1980
Doc. # 258582
Found GLO monument in good condition.
13" White Pine S46E 26.80';
8" Spruce S50W 10.40';
14" N. Pine N71W 49.90';
12" N. Pine N22E 42.90'