| Index No. JZ/ CASS COUNTY LAND | CORNER RECORD |
|----------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|
| T. 144 R. 27 M. 574 Coordinates: X <u>NE 14</u> Corner common to sections 11,12,13,14 | Y |
| | |
| | SURVEYS // |
| Original Government Survey | Original Evidence Found |
| Year surveyed 1873 | Year of search By |
| Original monument_lost | Monument found |
| Species Iam Bearing Trees | Original Bearing Trees Found O = Corner Species |
| Diameter 5" 5" | Diameter |
| Bearing N30E N39W | Bearing |
| Distance 75 LFS 62 LKS | Distance |
| Subsequent Corner Restoration | Evidence of Subsequent Corner Restoration |
| Variable 1937 B. (6/ 0 | Year of search By |
| Year surveyed 1937 Location filed Sec. Of State Monyment Find N. W. B.T. (Down) Set Concrete man | ledi vi sedicii |
| Location filed SC. U. S. C. + C. | |
| Monument Ind N. W. Pill Down) SCI Concrete man | |
| 21 long 6" Dra w/brass cap T144N 127W | |
| <u> </u> | |
| 5/4 5/3 | |
| Bearing Trees, Reference Objects 1937 | Bearing Trees, Reference Objects |
| a lower little satisfy Town | |
| Diameter 4" 6" 5" | |
| Diameter | |
| Bearing N25/2E 517/4E 52/2W N65W | |
| Distance 761KS 1841KS 176 LKS 1261KS | |
| | |
| Subsequent Corner Restoration Year surveyed By Location filed Monument | Evidence of Subsequent Corner Restoration Found Year of search By |
| | |
| | 1 |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| **** | <u></u> |
| | |
| | |
| | * · · · · · · · · · · · · · · · · · · · |
| | A |
| | |
| | |
| | |
| | |
| | · · · · · · · · · · · · · · · · · |
| | |
| | |
| | |
| | |
| Remonumentation certificate prepared | |