


Index No. R19

CASS COUNTY LAND CORNER RECORD

T. 144 R. R7 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1426 Corner common to sections 23,26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter NO trees  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1937 By GLO  
Location filed Sec. of State  
Monument Set 1x36" 1 1/2" willow sap 1/2 523  
1/2 526  
1937

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman  
Found GLO monument and BT in good condition.

Bearing Trees, Reference Objects

Species Pr. Oak  
Diameter 14"  
Bearing N39 3/4 W  
Distance 63 LKS

Bearing Trees, Reference Objects

OAK  
6"  
S80 E  
92.9'

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - OKERMAN - 1966

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_