Index No. R21

CASS COUNTY LAND CORNER RECORD

T. 144 R. 27 M. 5TH Coordinates: X _____ Y _____

NE 26 Corner common to sections 23, 24, 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Bearing Trees

Species	Tam	Spruce	Cedar	Cedar
Diameter	12"	5"	6"	4"
Bearing	S68E	S30W	N28E	N70W
Distance	12 LKS	22 LKS	18 LKS	25 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1937 By GLO

Location filed Sec. of State

Monument Set Concrete mon 2' long 6" Dia w/brass Cap

T144N R27W

523 | 524

526 | 525

Bearing Trees, Reference Objects 1937

Species	Cedar	Cedar	Cedar	Cedar
Diameter	8"	7"	8"	10"
Bearing	N57½E	S45E	S4W	N21W
Distance	53 LKS	46 LKS	39 LKS	24 LKS

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed

Monument

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____