


Index No. C-D 25

CASS COUNTY LAND CORNER RECORD

T. 144 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC Corner common to sections 1, and 6-144-27



O = Corner

EXISTING SURVEYS

Original Government Survey  
Year surveyed 1  
Original monument \_\_\_\_\_

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1937 By GLD  
Location filed Sec. of State  
Monument Set 1x36" 1R. W. brose gap MC  
S1 | S6  
R28W R27N  
T144N  
1937

Evidence of Subsequent Corner Restoration  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
Species Elm Cedar  
Diameter 7" 12"  
Bearing S41W N60W  
Distance 63 LBS 119 LBS

Bearing Trees, Reference Objects

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_