Index No. J 15

# CASS COUNTY LAND CORNER RECORD

T. 14 N R. 28 M. 5TH Coordinates: X _____ Y _____

N1/4 15 Corner common to sections 10/15




## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1873

Original monument Post

### Original Evidence Found

Year of search _____ By _____

Monument found _____

| Bearing Trees | | | | | | | |
|---|---|---|---|---|---|---|---|
| Species | Maple | | Fulsom | | | | |
| Diameter | 4" | | 4" | | | | |
| Bearing | N65W | | S10E | | | | |
| Distance | 20 LKS | | 15 LKS | | | | |

| Original Bearing Trees Found | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1931 By _____

Location filed _____

Monument Co DITCH SURVEY BK 171 BOX 3
OF Co DITCH SURVEY BOOKS PG 15 + 38

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Bearing Trees, Reference Objects

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____