


Index No. J 23

CASS COUNTY LAND CORNER RECORD

T. 144 R. 28 M. 574 Coordinates: X _____ Y _____
N1/4 13 Corner common to sections 12, 13



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees		
Species	<u>Tam</u>	<u>Cedar</u>	_____	_____
Diameter	<u>5"</u>	<u>3"</u>	_____	_____
Bearing	<u>S19W</u>	<u>N11W</u>	_____	_____
Distance	<u>33 LKS</u>	<u>19 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____