Index No. L 25

CASS COUNTY LAND CORNER RECORD

T. 144 R. 28 M 5TH Coordinates: X _____ Y _____

E1/4 13 Corner common to sections 13/18 - 144-27



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species _____

Diameter In lake in orig Survey

Bearing _____

Distance _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1937 By GLO

Location filed Sec. of State

Monument Set 1X36" 1/2 in. w/brass cap 1/4 513/518 1937

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Cedar Post

Diameter 6' long 4" Square

Bearing North ↓

Distance along side of post

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____