


T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 11 Corner common to sections 11, 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Bearing Trees

Species	<u>J. Pine</u>	<u>J. Pine</u>	
Diameter	<u>10"</u>	<u>10"</u>	
Bearing	<u>S 87W</u>	<u>N 87W</u>	
Distance	<u>14 LKS</u>	<u>41 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1926 By GLO
Location filed Sec. of State
Monument Find old stake: 8.75' 12" Dead J. Pine N 5-30E 22 LKS, 12" Dead J. Pine S 33W 19 LKS. These are not orig - but best available evidence - Set 1 X 3/8" I.P. w/ brass cap

Bearing Trees, Reference Objects ¹⁴ ₁₉₂₆

Species	<u>J. Pine</u>	<u>N. Pine</u>	
Diameter	<u>12"</u>	<u>12"</u>	
Bearing	<u>S 49E</u>	<u>S 56-15W</u>	
Distance	<u>48 LKS</u>	<u>59 LKS</u>	

Evidence of Subsequent Corner Restoration

Year of search 1961 By Pete Meyer
Found GLO monument in good condition

Bearing Trees, Reference Objects

<u>Oak</u>	<u>Red Pine</u>	<u>Cedar Post</u>
<u>7"</u>	<u>1 1/2"</u>	<u>4" x 4" x 78"</u>
<u>N 5E</u>	<u>S 53W</u>	<u>WEST</u>
<u>26.3'</u>	<u>38.9'</u>	<u>0.75'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1961