


Index No. H 17

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____
S 1/16 Corner common to sections 10, 11



EXISTING SURVEYS

Original Government Survey
Year surveyed 1926
Original monument 1136" 11D. W. cross cap 5 1/16
510/511
1926

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species Cedar Cedar
Diameter 6" 6"
Bearing S79E S32-30W
Distance 31Lks 50Lks

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

○ = Corner

Subsequent Corner Restoration
Year surveyed 1961 By PETE MEYER
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

Bearing Trees, Reference Objects
Species Cedar Ash
Diameter 8" 7"
Bearing S18E N64W
Distance 65.3' 30.4'

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - PETE MEYER, 1961