


Index No. R5

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 30 Corner common to sections 19, 20, 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Species	Bearing	Tree	Distance
<u>Tam</u>	<u>547E</u>	<u>6"</u>	<u>24 LKS</u>
<u>Ash</u>	<u>544W</u>	<u>5"</u>	<u>105 LKS</u>
<u>Tam</u>	<u>N50W</u>	<u>12"</u>	<u>39 LKS</u>
<u>Tam</u>	<u>N17E</u>	<u>4"</u>	<u>21 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Bearing	Tree	Distance

Subsequent Corner Restoration

Year surveyed 1906 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK "A" P242-243
Monument FRANCOIS GALT B.T.S: 6" TAM 547E 15.8'; 5" ASH N44W 69.3'; 12" TAM N50W 25.7'; 4" TAM N17E 13.9'
SET WOOD STAKE

Evidence of Subsequent Corner Restoration

Year of search 1926 By GLO
1/4 NW 61T, Sng 9 SE AND ONE B.T.S - NOW 10" x 8"
SET 2 x 36" 11P. W/ BRASS CAP T144N R29W
519/530
530/529

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

SPRUCE
6"
57-45
26 LKS

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1963
Found GLO monument in good condition
12" Tamarack N20E 13.86' (original);
6" Tamarack S63E 32.1';
6" Ash S80W 20.85';
7" Ash N30W 17.4'.

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____