


Index No. R.0-15.0

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

N 1/4 27 Corner common to sections 22, 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

| | | |
|----------|-----------------|----------------|
| Species | <u>Sugar</u> | <u>Linden</u> |
| Diameter | <u>12"</u> | <u>6"</u> |
| Bearing | <u>N 15° E</u> | <u>S 68° E</u> |
| Distance | <u>17 links</u> | <u>8 links</u> |

Original Bearing Trees Found

| | | |
|----------|-------|-------|
| Species | _____ | _____ |
| Diameter | _____ | _____ |
| Bearing | _____ | _____ |
| Distance | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 6/1930 By H.D. Craig, US Surveyor
 Location filed: Minn. Hist. Society, notes pg 103
 Monument: Set 1"x 36" iron pipe with brass cap up 6", at proportionate distance and marked new witnesses as follows.

1/4 S22
S27
1930

Evidence of Subsequent Corner Restoration

Year of search 11/1931 By G. Ryes, Estimator CCC
 Location filed: Form 874-9
 Monument: Found metal hub up 12", in good condition, 15 chains S. of old rd. to Sucker Bay and notes witnesses as follows.

Bearing Trees, Reference Objects

| | | |
|----------|-----------------|--------------------|
| Species | <u>Maple</u> | <u>Red Oak</u> |
| Diameter | <u>8"</u> | <u>22"</u> |
| Bearing | <u>N 76° E</u> | <u>S 26 1/4° E</u> |
| Distance | <u>94 links</u> | <u>98 links</u> |

Bearing Trees, Reference Objects

| | | |
|----------|-----------------|------------------|
| Species | <u>Maple</u> | <u>Red Oak</u> |
| Diameter | <u>7"(1930)</u> | <u>19"(1930)</u> |
| Bearing | <u>N 67° E</u> | <u>S 27° E</u> |
| Distance | <u>55'</u> | <u>55'</u> |

Subsequent Corner Restoration

Year surveyed 1963 By Gamache
 Location filed: USFS Book 1, page 69, 5680-11
 Monument:
 6/1991, C.R. Krause, USFS
 USFS Book 1, page 69
 Found GLO brass capped iron pipe, up 14", 15' S. of trail intersection, witnesses fall in clear cut, placed 3 large rocks around corner, new witnesses as follow.
 Steel Sign Post, North, 3.0' signs attached
 Steel Sign Post, East, 3.0' signs attached
 Steel Sign Post, West, 3.0' signs attached


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed:
 Monument:

Index No. R 15

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/4 27 Corner common to sections 22, 27



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1875
Original monument Post

Year of search _____ By _____
Monument found _____

| Species | Bearing | Trees |
|--------------|-------------|-------|
| <u>Sugar</u> | <u>Lynn</u> | _____ |
| <u>12"</u> | <u>6"</u> | _____ |
| <u>N15E</u> | <u>S68E</u> | _____ |
| <u>17LKS</u> | <u>8LKS</u> | _____ |

| Species | Original Bearing Trees Found | | |
|---------|------------------------------|-------|-------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

O = Corner

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed Sec. of State
Monument Set 1x36" 1/4" w/ brass cap 1/4 S22
1/4 S27
1930

Year of search _____ By _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

| Species | Bearing | Reference Objects |
|--------------|------------------|-------------------|
| <u>Maple</u> | <u>R. Oak</u> | _____ |
| <u>8"</u> | <u>22"</u> | _____ |
| <u>N76E</u> | <u>S26 1/4 E</u> | _____ |
| <u>94LKS</u> | <u>98LKS</u> | _____ |

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____