Index No. T.0-09.0 CASS COUNTY LAN	ID CORNER RECORD
	Y
E 1/4 29 Corner common to sections 28, 29	
	IG SURVEYS
Original Government Survey	Original Evidence Found
Year surveyed <u>1875</u>	Year of search by
Original monument Post	Monument found : : : : : : : : : : : : : : : : : : :
Bearing Trees	Original Bearing Trees Found
Species <u>Spruce</u> <u>Tamarack</u>	Species
Diameter 6" 8"	Diameter
Bearing N 72° E N 38° W	Bearing
Distance 8 links 18 links	Distance
Subsequent Corner Restoration	Fuidance of Subagguent Corner Restoration
·	Evidence of Subsequent Corner Restoration
Year surveyed 6/1930 By H.D. Craig, US Surveyor Location filed: Minn. Hist. Society, notes	Year of search 10/1934 By C.R. DuBois, Compassman CCC Location filed: Form 874-9
Monument: Set 1"x 36" iron pipe with brass cap 1/4	Monument: Found Brass iron pipe
up 6", at proportionate position and marked S29 S28 new witnesses as follows. 1930	up 7" in good condition, placed metal location poster on NW tree and notes witnesses as follow.
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species Spruce Spruce	Species Black Spruce Black Spruce Black Spruce
Diameter 5" 8"	Diameter 6"(1930) 4"(1930) 6"
Bearing N 75 3/4° E N 39 1/4° W	Bearing N 40°30' W N 76°20' E N 20°30' W
Distance 25 links 14 links	Distance 13 1/2 links 25 links 13 1/2 links
Outransport Company Deutstarting	Skiden on of Oak as accord Oam on Dock as five Second
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed 3/1975 By C.R. Krause, USFS	Year of search By
Location filed: USFS Book 1, page 51 Monument: Found iron with cap	Location filed: Monument:
up 6" in good condition, in swamp, at base of 6" Black Spruce cut off, 1100' S. of wood road and witnesses as follows. 10" Black Spruce, N 39° W, 9.2'(1930) scribe visible 7" Black Spruce, N 76° E, 16.5'(1930) windfall scribe visible 8" Birch, N 2° W, 1032' FSLP	
Certificate of Location of Government Corner filed in Cass County Recorders Office as Document	By Date

T9	
dex No. <u>T9</u> CASS COUNTY L	LAND CORNER RECORD
144 R 30 M 574 Coordinates: X	
144 R. 30 M. 574 Coordinates: X E'14 29 Corner common to sections 28,29	
	29
	TING SURVEYS
Original Government Survey	Original Evidence Found
ear surveyed 1873	Year of searchBy
riginal monument 105T	Monument found
	O = Corner
Species Struce Tam	Original Bearing Trees Found
Nomator 6 (1 81)	Diameter
Bearing N72E N38W	Bearing
Distance BLKS 18LKS	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
ear surveyed 1930 By GLO ocation filed Sec. of State	Year of search By
Appument Set 1X36" 11P. Waruss Cap 114.	
Monument Set 1X36" /IP. wbress cap 1/4.	
1930	
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
pecies Struce Spruce	
Diameter 5'' 8"	
7101116161	
Bearing N753/yE N39/4/W	
Bearing <u>N757yE</u> <u>N391kyw</u> Distance <u>25 LKS</u> <u>14 CkS</u>	Fuidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration Year surveyed By	Evidence of Subsequent Corner Restoration Found Year of search By
Subsequent Corner Restoration Year surveyed By	
Subsequent Corner Restoration Year surveyed By	
Subsequent Corner Restoration Year surveyed By	
Subsequent Corner Restoration Year surveyed By	
Subsequent Corner Restoration Year surveyed By	
Subsequent Corner Restoration Year surveyed By	
Subsequent Corner Restoration Year surveyed By	
Subsequent Corner Restoration Year surveyed By	
Subsequent Corner Restoration Year surveyed By	
Subsequent Corner Restoration Year surveyed By	Year of search By
Subsequent Corner Restoration Year surveyed By	Year of search By
Subsequent Corner Restoration Year surveyed By	Year of search By
Subsequent Corner Restoration Year surveyed By	Year of search By
Subsequent Corner Restoration Year surveyed By	Year of search By
Subsequent Corner Restoration Year surveyed By	Year of search By
Subsequent Corner Restoration Year surveyed By	Year of search By
Subsequent Corner Restoration Year surveyed By	Year of search By
Subsequent Corner Restoration Year surveyed By	Year of search By
Subsequent Corner Restoration Year surveyed By	Year of search By
Subsequent Corner Restoration Year surveyed By	Year of search By
Subsequent Corner Restoration Year surveyed By	Year of search By