


Index No. J1

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X _____ Y _____
NW 18 Corner common to sections 7, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Bearing Trees

Species	<u>Sugar Maple</u>	<u>Sugar Maple</u>	<u>Sugar Maple</u>	<u>Sugar Maple</u>
Diameter	<u>7"</u>	<u>7"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>N50E</u>	<u>S10E</u>	<u>S12W</u>	<u>N85W</u>
Distance	<u>11 LKS</u>	<u>8 LKS</u>	<u>13 LKS</u>	<u>3 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK 8 P. 36-39
Monument Four 3" TAM STAKE SET BY MIDDLETON AND OLD GOVT. B.T.S. 7" SUGAR MAPLE N50E 11 LKS, 6" SUGAR MAPLE S12W 13 LKS,

Evidence of Subsequent Corner Restoration

Year of search 1973 By CO. HWY DEPT
CO. PD #69
CORNER
may 1918, Twp rd order shows no survey.

Bearing Trees, Reference Objects

Species	<u>BIRCH</u>	<u>POPULAR</u>	<u>BASSWOOD</u>	<u>BASSWOOD</u>
Diameter	<u>8"</u>	<u>10"</u>	<u>16"</u>	<u>8"</u>
Bearing	<u>S46-30W</u>	<u>N48-30E</u>	<u>N44-30W</u>	<u>S69E</u>
Distance	<u>47.72'</u>	<u>56.69'</u>	<u>48.55'</u>	<u>43.50'</u>

Bearing Trees, Reference Objects

Elm	<u>OAK</u>	<u>OAK</u>
<u>24"</u>	<u>16"</u>	<u>24"</u>
<u>NE</u>	<u>NW</u>	<u>SW</u>
<u>100.5'</u>	<u>83.9'</u>	<u>95.2'</u>

J1

Subsequent Corner Restoration

Year surveyed 2/2001 By CCSO
Location filed CCSO
Monument Found Hubbard Co. CIM FLUSH, 05' N. of E CR #21 on E 72nd Ave. Witness as follows

16" W. Oak N44°W 83.87 Nailed disk 1973
19" R. Oak S20°W, 95.19 Nailed disk 1973
8" R. Oak S19°E, 112.13 *
Tel Red Post N30°E, 57.50 *
* distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____