


Index No. N5

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 19 Corner common to sections 17, 18, 19, 20



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1875

Original monument post

Species	Bearing	Trees
<u>N. Pine</u>	<u>15° 30'</u>	<u>W. Pine</u>
<u>16"</u>	<u>6"</u>	<u>Br. Oak</u>
<u>N 29° W</u>	<u>N 42° E</u>	<u>5 3° E</u>
<u>260 LKS</u>	<u>57 LKS</u>	<u>321 LKS</u>

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1931 By GLO

Location filed Sec. of State

Monument End Cass Co. 2" lip set concrete man  
26" long 6" dia w/ brass cap 2" below road surface  
reset pipe next to man.

T144N R31W  
S18/517  
S19/520

Species	Bearing	Trees	Reference Objects
<u>Birch</u>	<u>W. Pine</u>	<u>N. Pine</u>	<u>W. Pine</u>
<u>4"</u>	<u>5"</u>	<u>10"</u>	<u>5"</u>
<u>N 66 1/4° E</u>	<u>S 48 1/4° E</u>	<u>S 57 1/2° W</u>	<u>N 22 1/4° W</u>
<u>47 LKS</u>	<u>58 LKS</u>	<u>43 LKS</u>	<u>100 LKS</u>

**Evidence of Subsequent Corner Restoration**

Year of search 4/2001 By CCSO

Found 7 1/8" ODIP cap RLS 14700, down  
0.4', 2'± S. of & CR #141 and 2' W.  
of & CR #143.

Species	Bearing	Trees	Reference Objects
<u>W. Pine</u>	<u>P. Pole</u>	<u>W. Pine</u>	<u>W. Pine</u>
<u>15"</u>	<u>14"</u>	<u>16"</u>	<u>16"</u>
<u>N 22° W</u>	<u>N 41° E</u>	<u>S 53° E</u>	<u>S 38° W</u>
<u>65.77'*</u>	<u>47.45'*</u>	<u>57.97'*</u>	<u>39.11'*</u>

\*distance to double head nail

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument December 1998; T. Freeman # 21367  
Cert of Survey shows monument found

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_