


Index No. 0 21

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1116 Corner common to sections 23,24



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1930 N1116  
 Original monument 1x36" 11P. w/brass cap 523/524  
1930

**Bearing Trees**

Species	<u>Tam Shay</u>	<u>J. Pine</u>	_____
Diameter	<u>8"</u>	<u>4"</u>	_____
Bearing	<u>N58-15E</u>	<u>S84-30W</u>	_____
Distance	<u>234Lks</u>	<u>23Lks</u>	_____

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

By \_\_\_\_\_ Date \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Remuneration certificate prepared \_\_\_\_\_

Year surveyed \_\_\_\_\_ Location filed \_\_\_\_\_ Monument \_\_\_\_\_

Subsequent Corner Restoration