Index No. V9

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X _____ Y _____

NE 32 Corner common to sections 28, 29, 32, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	Spruce	Tam		
Diameter	4"	3"		
Bearing	N67E	East		
Distance	950 LKS	800 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURO

Location filed COUNTY RESURVEY PLAT "E-66"

Monument CEDAR POST

1915 CURO, BOOK "C" P. 489 FND TAM. B.T. SET 7"x30" CEDAR POST 20 FEET IN GROUND.

also on microfilm - roll 115 BK87 P. 35-36 - 9/50

Fnd NE B.T.

Evidence of Subsequent Corner Restoration

Year of search 1931 By GLO

Set Concrete mon. 24" long 6" Dia w/brass Cap

T144N R31W

529 | 528

532 | 533

1931

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Tam post 4"SQ

7' high alongside mon

528 on NE face 533 on SE face

532 on SW face 529 on NW face

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____