


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R 25

CASS COUNTY LAND CORNER RECORD

T. 145 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 25 Corner common to sections 24, 25 AND 19, 30 - 145 - 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	<u>Y. Pine</u>	<u>J. Pine</u>	<u>Y. Pine</u>	
Diameter	<u>6"</u>	<u>14"</u>	<u>6"</u>	<u>14"</u>
Bearing	<u>S10E</u>	<u>S42W</u>	<u>N7E</u>	<u>N12W</u>
Distance	<u>130LKS</u>	<u>129LKS</u>	<u>250LKS</u>	<u>385LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1958 By PETE MEYER
Location filed _____
Monument Set 2" x 5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Elm</u>	<u>Elm</u>	<u>Elm</u>	<u>Elm</u>
Diameter	<u>7"</u>	<u>7"</u>	<u>7"</u>	<u>8"</u>
Bearing	<u>N13 1/2 W</u>	<u>S168 1/2 W</u>	<u>S22E</u>	<u>N73 1/2 E</u>
Distance	<u>76.5'</u>	<u>42.2'</u>	<u>54.2'</u>	<u>60.3'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By CERTIFICATE - PETE MEYER - 1958

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____