

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. V21

CASS COUNTY LAND CORNER RECORD

T. 145 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 35 Corner common to sections 25, 26, 35, 36



EXISTING SURVEYS

Original Government Survey
Year surveyed 1873
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	Jack	Tam	Spruce	
Diameter	<u>16"</u>	<u>5"</u>	<u>3"</u>	<u>3"</u>
Bearing	<u>N2E</u>	<u>N6W</u>	<u>S21W</u>	<u>S19E</u>
Distance	<u>36 LKS</u>	<u>38 LKS</u>	<u>30 LKS</u>	<u>42 LKS</u>

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1958 By Pete Meyer
Location filed _____
Monument Set 2"x5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

Bearing Trees, Reference Objects				
Species	<u>Tamarack</u>	<u>Tamarack</u>	<u>Spruce</u>	<u>J. Pine</u>
Diameter	<u>6"</u>	<u>7"</u>	<u>8"</u>	<u>17"</u>
Bearing	<u>S75W</u>	<u>S26W</u>	<u>S34E</u>	<u>N18E</u>
Distance	<u>26.9'</u>	<u>20.4'</u>	<u>9.3'</u>	<u>11.7'</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1958