


Index No. \_\_\_\_\_

### CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

#### EXISTING SURVEYS

##### Original Government Survey

Year surveyed \_\_\_\_\_  
 Original monument \_\_\_\_\_

##### Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
 Monument found \_\_\_\_\_

##### Bearing Trees

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

##### Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

##### Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

##### Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

##### Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

##### Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

##### Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_


##### Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

Index No. P5

CASS COUNTY LAND CORNER RECORD

T. 145 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E/4 19 Corner common to sections 19, 20



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species J. Pine J. Pine  
Diameter 10" 10"  
Bearing S 71 1/2 W N 13 E  
Distance 19 LKS 204 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1937 By J. A. GUELHAUG  
Location filed Found oak post - scribed 2 Aspens  
Monument 1967 USPS Found 1937 evidence  
set 2x60" l.p. w/cap

Evidence of Subsequent Corner Restoration

Year of search 1979 By DNR-Engineering  
Found l.p. w/cap & 1937 blazed Aspen  
S 36 W 16.5'

Bearing Trees, Reference Objects

Species oak oak Aspen  
Diameter 5" 5" 8"  
Bearing East N 15 W S 26 W  
Distance 132.1' 102.85' 40.2'  
1967 TIES

Bearing Trees, Reference Objects

P-5

Subsequent Corner Restoration

Year surveyed 1986 By Walt Curo  
Location filed Corner Certificate - Doc # 291634  
Monument Find 2" l.p. as set in 1967  
5" N. Pine N 12° E 9.31'  
8" N. Pine N 55° E 27.58'  
5" Aspen S 85° W 14.92'  
5' steel sign post South 5.0'  
8' fiberglass post West 5.0'

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Walt Curo - 1986

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_