

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. A15

CASS COUNTY LAND CORNER RECORD

T. 145 R. 29 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 3 Corner common to sections 3 and 34-146-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument lost

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>J. Pine</u>	_____	_____
Diameter	<u>5"</u>	_____	_____
Bearing	<u>N35W</u>	_____	_____
Distance	<u>6 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1934 By GLO  
Location filed Sec. of state  
Monument Set 2x36" 1/4" w/ brass cap 1/4 534  
53  
1934

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman  
Found GLO monument in good condition  
Set 4"x4"x5" Cedar post East 16.0'

Bearing Trees, Reference Objects

Species	<u>J. Pine</u>	<u>Pine Post</u>	_____	_____
Diameter	<u>7"</u>	<u>6"</u>	_____	_____
Bearing	<u>N78W</u>	<u>N7-23E</u>	_____	_____
Distance	<u>24 LKS</u>	<u>48 LKS</u>	_____	_____

Bearing Trees, Reference Objects

<u>R Pine</u>	<u>R Pine</u>	<u>R Pine</u>	<u>R Pine</u>
<u>8"</u>	<u>8"</u>	<u>7"</u>	<u>9"</u>
<u>N73W</u>	<u>S50W</u>	<u>N52E</u>	<u>S80E</u>
<u>24.5'</u>	<u>33.9'</u>	<u>40.5'</u>	<u>28.6'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - TED'S SUBDIVISION  
S.F. SORENSON 1948

CERTIFICATE - BILL OKERMAN - 1966

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_