


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. A 17

CASS COUNTY LAND CORNER RECORD

T. 145 R. 29 M. 574 Coordinates: X _____ Y _____
NE3 Corner common to sections 2, 3 and 34, 35-146-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Species	Bearing	Trees		
<u>Cedar</u>	<u>Fir</u>	<u>Cedar</u>	<u>Cedar</u>	
Diameter <u>12"</u>	<u>4"</u>	<u>12"</u>	<u>8"</u>	
Bearing <u>N29E</u>	<u>N53W</u>	<u>S58 1/2 W</u>	<u>S32E</u>	
Distance <u>9 LKS</u>	<u>12 LKS</u>	<u>4 LKS</u>	<u>7 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1934 By GLD
Location filed SEC OF STATE
Monument Set Concrete mon 24" long 6" Dia w/brass cap
T145N R29W
S34/S35
S3/S2

Bearing Trees, Reference Objects T145N 1934

Species	Bearing	Trees	Reference Objects
<u>J. Pine</u>	<u>N. Pine</u>	<u>Charred pine stem</u>	
Diameter <u>13"</u>	<u>7"</u>	<u>14"</u>	
Bearing <u>S44 3/4 E</u>	<u>S40W</u>	<u>N16 3/4 W</u>	
Distance <u>116 LKS</u>	<u>50 LKS</u>	<u>42 LKS</u>	

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____