


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. E 5

CASS COUNTY LAND CORNER RECORD

T. 145 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 7 Corner common to sections 5, 6, 7, 8



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>B. Pine</u>	<u>B. Pine</u>
Diameter <u>12"</u>	<u>10"</u>
Bearing <u>S37E</u>	<u>N45E</u>
Distance <u>336S</u>	<u>546S</u>

Original Bearing Trees Found			
Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1958 By Pete Meyer
Location filed _____
Monument Set 2" x 5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects			
Species <u>J. Pine</u>	<u>J. Pine</u>	<u>J. Pine</u>	<u>J. Pine</u>
Diameter <u>9"</u>	<u>10"</u>	<u>6"</u>	<u>7"</u>
Bearing <u>S12E</u>	<u>S58E</u>	<u>N80E</u>	<u>N34E</u>
Distance <u>48.0'</u>	<u>29.0'</u>	<u>53.5'</u>	<u>18.2'</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By CERTIFICATE - PETE MEYER - 1958

CERTIFICATE - TONY KERICK - 1961

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____