


Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X NE 4 Y 3, 4 AND 33, 34-146-30
Corner common to sections



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost

Species	Bearing	Tree	Distance
<u>J. Pine</u>	<u>7"</u>	<u>J. Pine</u>	<u>36 LKS</u>
<u>J. Pine</u>	<u>12"</u>	<u>J. Pine</u>	<u>40 LKS</u>
<u>J. Pine</u>	<u>8"</u>	<u>J. Pine</u>	<u>23 LKS</u>
<u>J. Pine</u>	<u>12"</u>	<u>J. Pine</u>	<u>10 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1933 By GLO
Location filed Sec. of State
Monument Set concrete mon 24" long 6" dia w/ brass cap
in center of Hwy

Evidence of Subsequent Corner Restoration

Year of search 4/1980 By USFS
Found concrete monument 1.8'
below road surface @ GLO Pine
S 84° W, witness as follow.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>R. Oak</u>	<u>3"</u>	<u>N 59 1/2 E</u>	<u>52 LKS</u>
<u>J. Pine</u>	<u>4"</u>	<u>S 48 E</u>	<u>84 LKS</u>
<u>J. Pine</u>	<u>14"</u>	<u>S 84 1/2 W</u>	<u>299 LKS</u>
<u>J. Pine</u>	<u>12"</u>	<u>N 11-40 W</u>	<u>331 LKS</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>J. Pine</u>	<u>10"</u>	<u>S 44° E</u>	<u>94.78*</u>
<u>J. Pine</u>	<u>10"</u>	<u>N 46° E</u>	<u>87.45*</u>
<u>J. Pine</u>	<u>10"</u>	<u>S 53° W</u>	<u>89.70*</u>
<u>J. Pine</u>	<u>10"</u>	<u>N 52° W</u>	<u>103.17*</u>

* distance to 16d spike

A 13

Subsequent Corner Restoration

Year surveyed 2/2001 By CCSO
Location filed CCSO
Monument Found brass cap flush 1' w
& CE #10 (Beltram Co.). Also found
1980 BT's.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____