


Index No. C-D 3

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
SMCON Corner common to sections 6  
N-S 1/4 Line



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1933

Original monument 1x36" 1/4 P.W. Brass

Species Br oak Br oak

Diameter 5" 6"

Bearing N33 3/4 E N16 3/4 W

Distance 88 LKS 80 LKS

*Handwritten notes: C, S, C, SMC, 1933, CAP*

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

**Bearing Trees, Reference Objects**

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Remuneration certificate prepared

Filed at \_\_\_\_\_

By \_\_\_\_\_

Date \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_