

T. 145 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/4 11 Corner common to sections 1, 11



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Blk. Pine</u>	<u>Blk. Pine</u>	_____
Diameter	<u>4"</u>	<u>4"</u>	_____
Bearing	<u>S 16° E</u>	<u>N 28° W</u>	_____
Distance	<u>42 links</u>	<u>56 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 6/1933 By W.W. Bandy, Surveyor

Location filed: Resurvey Notes

Monument: Set 1"x 36" iron post with brass cap at proportionate distance. S 2
1/4 _____
S 11
1933

Evidence of Subsequent Corner Restoration

Year of search 5/1966 By J. Ekstrom, USFS

Location filed: USFS Book 1, page 79

Monument: Found GLO brass cap and witnesses.
Steel Sign Post, S 88° W, 5.9'

Bearing Trees, Reference Objects

Species	<u>Jack Pine</u>	<u>Norway Pine</u>	_____
Diameter	<u>8"</u>	<u>18"</u>	_____
Bearing	<u>N 31° E</u>	<u>S 89 3/4° E</u>	_____
Distance	<u>138 links</u>	<u>318 links</u>	_____

Bearing Trees, Reference Objects

Species	<u>Jack Pine</u>	<u>Norway Pine</u>	<u>Oak</u>	<u>J. Pine</u>
Diameter	<u>15" (1933)</u>	<u>24" (1933)</u>	<u>6"</u>	<u>9"</u>
Bearing	<u>N 31° E</u>	<u>S 89° E</u>	<u>N 25° W</u>	<u>N 52° E</u>
Distance	<u>91.08'</u>	<u>209.88'</u>	<u>12.6'</u>	<u>43.7'</u>

Subsequent Corner Restoration

Year surveyed 8/1973 By C.R. Krause, USFS

Location filed: USFS Book 1, page 79

Monument: Found corner

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____


Location filed: _____

Monument: _____

Index No. E19

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
N1/4 11 Corner common to sections 2, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species B. Pine B. Pine
Diameter 4" 4"
Bearing S1/2 E N28W
Distance 42 LKS 50 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1933 By GLO
Location filed Sec of State
Monument Set 1x36" I.P. willow cap 1/4 S2
1/4 S11
1933

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman
Found GLO monument in good condition

Bearing Trees, Reference Objects

Species J. Pine N. Pine
Diameter 8" 18"
Bearing N31E S89 3/4 E
Distance 138 LKS 318 LKS

Bearing Trees, Reference Objects

Oak J. Pine
6" 9"
N25W N52E
12.6' 43.7'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1966

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____