


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/4 12 Corner common to sections 1, 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search 1933 by GLO
Monument found _____

Resurvey Notes

Bearing Trees

Species	<u>Black Pine</u>	<u>Yellow Pine</u>	_____	_____
Diameter	<u>12"</u>	<u>16"</u>	_____	_____
Bearing	<u>S 1° E</u>	<u>N 37° E</u>	_____	_____
Distance	<u>93 links</u>	<u>36 links</u>	_____	_____

Original Bearing Trees Found

Species	<u>Norway Pine</u>	_____	_____	_____
Diameter	<u>26"</u>	_____	_____	_____
Bearing	<u>N 37° E</u>	_____	_____	_____
Distance	<u>36 links</u>	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 6/1933 By W.W. Bandy, Surveyor

Location filed: Resurvey Notes

Monument: Set 1"x 36" iron post with brass cap S 1
from remains of original witnesses. 1/4 _____
S 12
1933

Bearing Trees, Reference Objects

Species	<u>Norway Pine</u>	<u>Norway Pine</u>	_____	_____
Diameter	<u>6"</u>	<u>8"</u>	_____	_____
Bearing	<u>N 79 1/2° E</u>	<u>S 15 1/2° E</u>	_____	_____
Distance	<u>19 links</u>	<u>24 links</u>	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 5/1936 By CCC

Location filed: Form 874

Monument: No stake
24" Norway tree scribed 1/4 S, no other trees evidence.

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 6/1966 By M. Hansey, USFS

Location filed: USFS Book 1, page 61

Monument: Found GLO brass cap
and witnesses.
N. Pine stump, N 37° E, 23.76' (GLO)
11" N. Pine, N 80° E, 12.54' (1933)
12" N. Pine, S 16° E, 15.84' (1933)

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____


Location filed: _____

Monument: _____

Index No. E 23

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 12 Corner common to sections 1 AND 12



EXISTING SURVEYS

Original Government Survey
Year surveyed 1874
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species Bl. Pine Y. Pine
Diameter 12" 16"
Bearing S 1 E N 37 E
Distance 93 LKS 36 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1933 By GLO
Location filed Sec. of State
Monument End NE B.T. - now 26" set 1 1/2" l.p.
w/brass cap
Cor. at edge of swamp bearing N 65
1/4 S 12
1933

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1966
Found GLO monument in good condition

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____