Index No. N 25

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____

NE 24 Corner common to sections 13, 24 AND 18, 19- 145 -29



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Bearing Trees

Species	Cedar	Cedar	Birch	Tam
Diameter	5"	5"	7"	7"
Bearing	N67½E	N47W	S64W	S42E
Distance	24 LKS	24 LKS	14 LKS	6 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1933 By GLO

Location filed Sec. of State

Monument Set Concrete mon 24" long 6" Dia w/brass Cap at intersection of blazed lines N-S i W Corner on S. Slope of R.R. embankment 32 LKS S. of ℄ of track T 145 N R 30 W R 29 W

S13 | S18 / S24 | S19

Bearing Trees, Reference Objects

Species	Ash	Spruce		
Diameter	9"	5"		1933
Bearing	S48E	S23¾W		
Distance	83 LKS	49 LKS		

Evidence of Subsequent Corner Restoration

Year of search 1961 By Pete Meyer

Found GLO monument in good condition.

Bearing Trees, Reference Objects

Cedar Post 4"×4"×6½'	Cedar 7"		
S11W	S70W		
33.0'	70.4'		

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER - 1961

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____