Index No. R22 CASS COUNTY LAND	CORNER RECORD
T. 145 R. 30 M. 574 Coordinates: X  W'//6 Corner common to sections 24,25	Y
$w''/c$ Corner common to sections $\frac{29/23}{}$	
EXISTING	S SURVEYS 25
Original Government Survey	Original Evidence Found
Year surveyed 1933 11. 524	Year of searchBy
Year surveyed 1933 Original monument 1136"11P. w 1brass w 116 525 (4P 1933	Monument found
Species Br. oak N. line Diameter 5" 10" Bearing N3874E \$59344W	Original Bearing Trees Found  Species
Diameter 51/	Diameter
Distance 72 465 340665	Bearing Distance
Distance 7 A 905 54000 5	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
Year surveyed 1962 By Pete Meyer  Location filed	Year of searchBy
Monument Found GLO monument in good condition.	
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species R. Pine J. Pine	
Diameter 10" 10"  Bearing 525W N22'12E	
Distance 43.9' 35.3'	
Distance TO:	
Subsequent Corner Restoration  Year surveyed By	Evidence of Subsequent Corner Restoration Found  Year of search  By  CERTIFICATE - PETE MEYER - 1962
Location filed	CERTIFICATE - PETE MEYER- 1962
Monument	
1.00	
	What is the second of the seco
Remonumentation certificate prepared	By