


Index No. R 25

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 25 Corner common to sections 24, 25 and 19, 30 - 145-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

| Species  | Bearing Trees  |                |                |                |
|----------|----------------|----------------|----------------|----------------|
|          | <u>N. line</u> | <u>N. line</u> | <u>N. line</u> | <u>N. line</u> |
| Diameter | <u>18"</u>     | <u>14"</u>     | <u>12"</u>     | <u>24"</u>     |
| Bearing  | <u>N25E</u>    | <u>N36W</u>    | <u>S87W</u>    | <u>S54E</u>    |
| Distance | <u>9 LKS</u>   | <u>48 LKS</u>  | <u>23 LKS</u>  | <u>94 LKS</u>  |

Original Bearing Trees Found

|          |       |       |       |
|----------|-------|-------|-------|
| Species  | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing  | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1933 By GLO  
Location filed Sec. of State  
Monument FND NE, SW & NW 815 - now 20' 14"?  
16" - set concrete mon. 24" long 6" dia w/  
Dress cap  
7145N

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

| Species  | Bearing Trees, Reference Objects |                |                |                |
|----------|----------------------------------|----------------|----------------|----------------|
|          | <u>N. line</u>                   | <u>N. line</u> | <u>N. line</u> | <u>N. line</u> |
| Diameter | <u>5"</u>                        | _____          | _____          | _____          |
| Bearing  | <u>N36W</u>                      | _____          | _____          | _____          |
| Distance | <u>48 LKS</u>                    | _____          | _____          | _____          |

Bearing Trees, Reference Objects

|       |       |       |       |
|-------|-------|-------|-------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_