


T. 145 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 35 Corner common to sections 35, 36



26

● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument Post

Original Evidence Found

Year of search 1900 by COE  
Monument found \_\_\_\_\_

Winnibigoshish Reservoir Map

Bearing Trees

Species Birch Cedar  
Diameter 10" 10"  
Bearing N 69° W N 70° E  
Distance 14 links 10 links

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1900-03 By T.M. Fowble, COE  
Location filed: Leech Lake and Winnibigoshish Reservoir Map  
Monument:  
Map indicates a known corner.

Evidence of Subsequent Corner Restoration

Year of search 7/1933 By W.W. Bandy, Surveyor, GLO  
Location filed: MN Historical Society, Notes pg 18 1/4  
Monument: Set 1"x 3' iron pipe with brass cap S 35 | S 36  
At proportionate position, no original evidence, 1933  
up 9" and witnesses as follows.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species Spruce Spruce  
Diameter 8" 6"  
Bearing N 19 1/2° E N 82 1/4° W  
Distance 52 links 67 links

Subsequent Corner Restoration

Year surveyed 9/1976 By C.R. Krause, USFS  
Location filed: USFS Book 1, page 38  
Monument: Found GLO 1" iron pipe with brass cap  
up 10" in good condition, 350' SE. of Black Spruce swamp and  
witnessed as follows.  
10" Balsam, N 20° E, 34.3'(1933) scribe rotted out  
13" Balsam, N 82° W, 44.2'(1933) snag  
5" Ash, N 53° E, 58.45' marked  
7" Elm, S 56° E, 46.15' marked  
11" Elm, S 27° W, 56.4' marked  
3" Square Elm Post, beside iron


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed: \_\_\_\_\_  
Monument: \_\_\_\_\_

Index No. X 21

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 35 Corner common to sections 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Birch Cedar  
Diameter 10" 10"  
Bearing N69W N70E  
Distance 14LKS 10LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

○ = Corner

Subsequent Corner Restoration

Year surveyed 1933 By GLO  
Location filed Sec. of state  
Monument Set 1x36" 1/4 P. w/ brass cap  
1/4  
S 35/536  
1933

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species Spruce Spruce  
Diameter 8" 6"  
Bearing N19 1/2 E N82 1/4 W  
Distance 52LKS 67LKS

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - MILO STEFAN - 1976  
Doc. # 246229  
Found GLO monument in good condition  
5" Ash N53E 58.45';  
7" Elm S56E 46.15';  
11" Elm S27W 56.40'

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_