

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. E11

CASS COUNTY LAND CORNER RECORD

T. 145 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 9 Corner common to sections 4, 9



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1875  
 Original monument Post

Bearing Trees  
 Species J. Pine J. Pine  
 Diameter 10" 6"  
 Bearing N8W S16E  
 Distance 120 LKS 48 LKS

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1907 By John Curo  
 Location filed County Survey Record Book "D" PRB2-283  
 Monument SET POST FROM OLD GOVT BITS: 10" J. PINE  
N8W 79.2', 6" J. PINE S16E 31.7'  
1913, Curo, Book "D" P. 152 - NO STUMPS OF BOTH GOVT BITS.  
SET 1 1/2" x 4 1/8" CAPPED GALV. I.P.

Bearing Trees, Reference Objects  
 Species 1913 - also on microfilm - roll 115 BK 74  
 Diameter \_\_\_\_\_ P. 81  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
 Year of search 11/2001 By CCSO  
Found C.I.M., FLUSH 1' E.S. of & CR #60,  
1' E. of & 63rd Ave. 1993 witnesses  
NE & SE are good, add following

Bearing Trees, Reference Objects  
 N. Pine 8" J. Pine 4"  
N 68°W S 20°W  
87.22'\* 77.42'\*  
 \*distance to double head/square disk

E-11

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - PINE GROVE CEMETARY - CASS LAKE  
- JOHN CURO 1914  
PAB-10-28: Found 1 1/4" capped pipe 34" below hwy.  
surface. Left monument as found. Placed  
MNDOT Cast iron monument above existing  
capped pipe. Top of monument flush w/ hwy.  
surface. 4-26-94 Cert. Filed by Robert  
Murray, RLS 15483, Doc. # 359110. Ties:  
12" Jack Pine N58E 74.72; 12" Jack Pine S46W  
70.43; Power Pole S54E 60.05

Nov 1996  
MNDOT RIGHT of WAY PLAT NO. 11-18

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_