


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:

Year of search _____ By _____
Location filed:
Monument:

T. 145 R. 31 M. 574 Coordinates: X _____ Y _____
E14 Corner common to sections 9, 10



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1875
 Original monument Post

Bearing Trees
 Species Jilne Jilne
 Diameter 8" 6"
 Bearing S59W N40E
 Distance 8 LKS 10 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1913 By Curo.
 Location filed County Book "D" P. 151
 Monument Find IRON PREVIOUSLY ESTABLISHED BY Curo
also on microfilm - roll 115 BX74 P. 79, 92-93

Evidence of Subsequent Corner Restoration
 Year of search 11/2001 By CCSO
Found CIM, down 0.1' on E CR #60,
1'E.N. of E 162nd St. 1983 trees gone

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects
N. Pine P. Pole P. Pole
12"
N30°W N5°E S43°E
78.50' 232.82' 53.69'
*distance to double head nail

G-13

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
PLAT - PINE GROVE CEMETARY - CASS LAKE
JOHN Curo 1914

PLAT - TRACT 33 SUBDIVISION
DOUGLAS STEWART 1966
1993 10-25: Found 1 1/4" capped pipe 15" below
surface of highway. 10-25-93 placed a
MnDOT cast iron monument above existing
capped pipe. Top of monument flush w/ hwy.
surface. 4-26-94 Cert. Filed by: Robert
Murray, RLS 15483, Doc # 357115. Ties:
10" Norway N25W 78.42; 11" Norway S54E
105.63