Index No. $R//$ CASS COUNTY	LAND CORNER RECORD
- 1118 - 21 571	
T. <u>145</u> R. <u>31</u> M. <u>574</u> Coordinates: X <u>N/4 28</u> Corner common to sections <u>21,26</u>	
10.79 2 Corner common to sections 2 1/20	
EXIS	STING SURVEYS
Original Government Survey	Original Evidence Found
Year surveyed 1875	Year of search By
Original monument Post	Monument found
Begring Trees	Original Bearing Trees Found O = Corner
Species Juline Juline	Species
Diameter 8" /2"	Diameter
Bearing 5/3W N/3E	
Distance 216US 270US	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
Year surveyed By	Year of search 2000 By CCSO
Location filed	I tad inplace; 2" telspar mon. Alum. cap
Monument	RLS&1_83, down O.6'. Located 2'N &
· · · · · · · · · · · · · · · · · · ·	C.R. 146. Fnd. survey mkr. sign post 23'So.
	of monument.
Bearing Trees, Reference Objects	N. Pine N. Pine N. Pine SVV mkr.
Species	N. Pine N. Pine N. Pine Svy mkr.
Diameter	N 55°W S 46°E S 72°W SOUTH
Bearing	90.58' 51.14' 114.02' 23.0'
Distance	(TAG)
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed By	Year of search By
Monument	
Dames and Addison and Addison	
Remonumentation certificate prepared	By