

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found


Year of search _____ By _____
Location filed:
Monument:

Index No. R9

CASS COUNTY LAND CORNER RECORD

T. 146 R. 27 M. 5TH Coordinates: X _____ Y _____

NE29 Corner common to sections 20, 21, 28, 29



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1874
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

| Species | Bearing | Trees | Distance |
|----------------|----------------|--------------|---------------|
| <u>N. Pine</u> | <u>N 1/2 W</u> | <u>7 1/2</u> | <u>60 LKS</u> |
| <u>N. Pine</u> | <u>S 23 W</u> | <u>6</u> | <u>57 LKS</u> |
| <u>N. Pine</u> | <u>N 59 E</u> | <u>7</u> | <u>60 LKS</u> |
| <u>w. Pine</u> | <u>N 21 W</u> | | |

Original Bearing Trees Found

| Species | Bearing | Distance |
|---------|---------|----------|
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

R-9

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1989 FILED IN 1978
Doc. # 246214
Set 6" x 6" concrete monument with
bronze tablet.
7" Jack Pine N 75.5 W 33.10'
8" Red Pine N 60.5 E 41.20'
8" Red Pine N 25 E 36.60'

Re monumentation certificate prepared _____ By _____
 Filed at _____ Date _____