

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

N-9
 5-N

~~CHIPPENAW~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 25 W 4th Mer.

1/4 Corner common to Sections

18, and 19

Corner consists of a 3/4" x 1" Iron Pipe in place

State condition good

Dimensions above ground 1 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. 19	GROWN OVER		
B.T.			

Species R. Pine R. Pine

Diameter 10" 14"

Bearing S 60° W S 18° E

Distance 279 Lks 276 Lks

Do you believe this to be a genuine Land Office Corner No

If not, why? records show it was set by County Surveyor.

Arthur J. Johnson

(Signature)

2/1/40

(Date)


Squad Foreman

(Title)

N-3

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

2
1
3

~~CHIPPENAW~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 25 W 4th Mer.

1/4 Corner common to Sections

18, and 19

Corner consists of a 3/4" x 1" Iron Pipe (cont) in place

State condition good

Dimensions above ground 1 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. 19	GROWN over		
B. T.			

Species R. pine R. Pine

Diameter 10" 14"

Bearing S 6° W S 18° E

Distance 279 lks. 276 lks

Do you believe this to be a genuine Land Office Corner? NO

If not, why? records show it was set by county surveyor.

Arthur J. Johnson
 (Signature)

Squad Foreman


(Title)

2/1/40

(Date)

N-3

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 57 N R. 25 W 4 th Mer.

Form 874-2—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

CHIPPEWA

N 3

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. **57 N** R. **25 W** **4 th** Mer.

1/4

Corner common to Sections

18

19

and

Corner consists of a **3/4" x 1" Iron Pipe** in place

State condition **Good**

Dimensions above ground **1** inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. 19	Grown over		
--------------	-------------------	--	--

B.T.			
-------------	--	--	--

Species **R. Pine R. Pine**
 Diameter **10" 14"**
 Bearing **S 6° W S 18° E**
 Distance **279 Lks 296 Lks**

Do you believe this to be a genuine Land Office Corner? **No**


If not, why? **records show it was set by County Surveyor.**

Arthur J. Johnson
 (Signature)
Squad Foreman

2/1/40

(Date)

(Title)



(Make sketch of topography near Corner)

T. 34 N. R. 28 W. Mer.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.