

U. S. Department of Agriculture  
FOREST SERVICE

N-23

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 25 W 4 th Mer.

$\frac{1}{4}$  Corner common to sections  
13, and 24

Corner consists of a 3" Scribed Post (not in place)

State condition POOR

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S. 15			
	N	W	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

GROWN over			
B. T.			

Species Aspen W. Spruce

Diameter 11" 16"

Bearing S67°E N75°W

Distance 99 Lks 176 Lks

Do you believe this to be a genuine Land Office Corner? NO.

If not, why? Records show it was set by  
county surveyor in 1925.

*Edward P. P.*  
(Signature)

11/21/39

(Date)

J. F. P. 1

(Title)

N-23

Original post nailed to side of new  
post 4" x 30" oak post set 11/21/39  
by Ed Penek.

Post set on South side of road.

Corner again.

Give any further facts which will aid in finding this


1.76 chains distant.

From which this Corner bears S 75° E

side of Road

tree 16 inches diameter, on the North

Metal Location Poster is on a W. Spruce



(Make sketch of topography near corner)

T. 57 N R. 25 W 4th Mer.

Form 874-9—Revised May, 1918.  
U. S. Department of Agriculture  
FOREST SERVICE

2  
23

**CHIPPENAW** NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. **57 N** R. **25 W** **4th** Mer.

$\frac{1}{2}$  Corner common to Sections  
**13**, and **24**

Corner consists of a **described post** in place

State condition **poor**

Dimensions above ground **24** inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

+ S. 13				
	N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<b>GROWN OVER</b>			
<b>B. T.</b>			

Species **Aspen** **N. Spruce**

Diameter **11"** **16"**

Bearing **S67°E** **N75°E**

Distance **99 lks** **176 lks**

Do you believe this to be a genuine Land Office Corner **No**

If not, why? **Records show it was set by county surveyor in 1925.**

*Edward P. J.*

(Signature)

**J. P. P. I**

(Title)

**11/21/39**

(Date)

N-23

Post set on South side of road.  
Original post nailed to side of new  
post 4" x 30" oak post set 11/21/39  
by Jd Parker.

Corner again.

Give any further facts which will aid in finding this


1.76 chains distant.

from which this Corner bears S 75° E

side of Road

tree 16 inches diameter, on the North

Metal Location Poster is on a W. Spruce



(Make sketch of topography near Corner)

T. 57 N R. 25 W 6 1/2 Mer.

U. S. Department of Agriculture

FOREST SERVICE

N 23

CHIPPENAW NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 25 W 4th Mer.

1/4 Corner common to Sections 13, and 24

Corner consists of a 3x3x3x3 post in place



State condition poor

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen W. Spruce

Diameter 11 16

Bearing S67°E N75°W

Distance 99 lks 176 lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Records show it was set by county surveyor in 1925.

Edward Tanski (Signature)

11/21/39

(Date)


J. P. P. J.

(Title)

Original post nailed to side of new  
post 4" x 30" oak post set 11/21/39  
by J. J. Penak.  
Post set on south side of road.

Corner again.  
Give any further facts which will aid in finding this  
chains distant.

1.76  
from which this Corner bears S 75° E  
side of Road  
16 inches diameter, on the North  
Metal Location Poster is on a W. Spruce



(Make sketch of topography near Corner)