

Form 841-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

N-25

~~CHIPPENAW~~ NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. ~~57 N~~ R. ~~25 W~~ 4th Mer.

Section Corner common to Sections

13 & 24 - 57 - 25, and 18 & 19 - 57 - 24

Corner consists of a 5"x12" scribed post (not) in place

State condition 1"x15" Iron Pipe post badly rotted but pipe good.

Dimensions above ground post on ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

		Not Readable	
--	--	-----------------	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

N. C.

GROWN
OVER

--

--

--

--

--

--

Species ~~Balsam~~ Ash

Diameter ~~10"~~ 7"

Bearing ~~N30° W~~ S10° W

Distance ~~74 lks~~ 33 lks

Do you believe this to be a genuine Land Office Corner? **No**

If not, why? records show it was set by county surveyor in 1925.

Edward J. F. P. 1

(Signature)

J. F. P. 1


(Title)

11/21/39

(Date)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

N-25
56-25

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. ~~56~~ 57 N. R. 25 W. 4 th Mer.

Section Corner common to Sections

13 & 24 - 57 - 25 and 18 & 19-57-24

3" x 12" Scribed post

Corner consists of a 1" x 6" Iron Pipe (not) in place

State condition Post badly rotted but pipe good.

Dimensions above ground Post on ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

		Not Readable	
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

W. C.	Grown over		

Species Balsam Ash
 Diameter 10" 7"
 Bearing N80° W S10° W
 Distance 74 lks 33 lks

Do you believe this to be a genuine Land Office Corner? No
 If not, why? Records show it was set by
 County surveyor in 1925.

Edward Panek

(Signature)

J. F. P. 1

11/21/39


(Date)

(Title)

N-25

Metal Location Poster is on a
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.

Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

T. 27 N R. 25 W 4 th Mer.

U. S. Department of Agriculture

FOREST SERVICE

CHIPPENAW NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 25 W 4th Mer.

Section Corner common to Sections

13 24 - 57 - 25, and 18 19 - 57 - 24

Corner consists of a 3"x12" scribed post (not) in place

State condition 1"x6" Iron Pipe post badly rotted but pipe good.

Dimensions above ground post on ground inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Balsam Ash

Diameter 10" 7"

Bearing N80° W S10° W

Distance 74 Lks 33 Lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? records show it was set by county surveyor in 1925.

Edward Jones (Signature)

(Signature)

J. F. P. I.

(Title)


11/21/39

(Date)

N-25

Metal Location Poster is on a
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.

Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

T. 27 N R. 25 W 4 1/4 Mer.