

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

5125

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 29E25W 4th. Mer.

Section Corner common to sections

7, 18, 12, and 13

Corner consists of a None (not) in place


State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

5.13	Grown over	Grown over	
B.T.			

Species R. Pine R. Pine R. Pine

Diameter 1 1/2" 1 1/2" 1 1/2"

Bearing S12°W N87°W N30°W

Distance 79 lks. 198 lks. 125 lks.

Do you believe this to be a genuine Land Office Corner? No

If not, why? Records show it was

set by County Surveyor

Arthur J. Johnson

(Signature)

Squad Foreman

(Title)

2/12/90

(Date)

J-25

Corner again.

Give any further facts which will aid in finding this

chains distant.

58.


from which this Corner bears

5 North

side of road

tree ~~cross diameter~~, on the North

Metal Location Poster is on a Location Post



(Make sketch of topography near Corner)

T. 51N. R. 22W. 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

7-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N. R29+25W. 4th Mer.

Section Corner common to Sections
7, 18, 12, and 13.

Corner consists of a None (not) in place


State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. 13

Grown over

Grown over

B.T.

Species R. Pine R. Pine R. Pine

Diameter 19" 19" 19"

Bearing S. 12° W. N 59° W. N 20° W.

Distance 221ks 1981ks 1251ks.

Do you believe this to be a genuine Land Office Corner? No.

If not, why? Records show it was set by

County Surveyor

Arthur J. Johnson

(Signature)

Special Foreman

(Title)

2/12/190

(Date)

J-1

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears 500 TH

side of Road

tree inches diameter, on the North

Metal Location Poster is on a location Post



(Make sketch of topography near Corner)

T. 57N R. 25W S. 76 Mer.

U. S. Department of Agriculture
FOREST SERVICE

J 25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N. R. 24+25W. 9th. Mer.

Section Corner common to Sections
7, 10, 12, and 13

Corner consists of a None (not) in place
State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. 13	Grown over	Grown over	
B.T.			

Species R. Pine R. Pine R. Pine

Diameter 14" 14" 19"

Bearing S 12° W N 54° W N 30° W

Distance 29 lks. 198 lks. 125 lks.

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by
County Surveyor.

Arthur J. Johnson

(Signature)


Squad Foreman

(Title)

2/12/40

(Date)

(Make sketch of topography near corner)



Metal Location Poster is on a location Post

tree inches diameter, on the North

side of road

from which this Corner bears South

132 chains distant.

Give any further facts which will aid in finding this

Corner again.

T. 57N R. 29E 25W 476 Mer.