

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

C-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N. R. 29+25W. 9th Mer.

Corner common to sections
1, and 6

Corner consists of a 1" Iron Pipe (rod) in place


State condition Good

Dimensions above ground 29" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? **NO**

If not, why? **Records show it was set by County Surveyor**

2/19/90
(Date)

Arthur J. Johnson
(Signature)
Squad Foreman
(Title)

C-25

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57N R. 19E 25W 47th Mer.

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *57N* R. *29+25W* *9th* Mer.

1/4 Corner common to Sections
1, and *6*


Corner consists of a *1" Iron Pipe* (not) in place
State condition *Good*

Dimensions above ground *29* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *NO*

If not, why? *Records show it was set by County Corner*

Arthur J. Johnson

(Signature)

Squad Foreman

(Title)

2/19/40


(Date)

C-25

Corner again.

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 52N. R29+25W. 9th Mer.

U. S. Department of Agriculture

FOREST SERVICE

C-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 29&25W 4th Mer.

 $\frac{1}{4}$

Corner common to Sections

1, and 6

Corner consists of a 1" Iron Pipe (not) in place

State condition Good

Dimensions above ground 29 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____


Do you believe this to be a genuine Land Office Corner? NOIf not, why? Records show it was setby County Surveyor

Arthur J. Johnson

(Signature)

2/19/40
(Date)Special Foreman
(Title)

(Make sketch of topography near Corner)



T. 57N R. 29E W. 5th. Mer.

Metal Location Poster is on a tree _____ inches diameter, on the side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.