

U. S. Department of Agriculture  
FOREST SERVICE

N. 15-16

CHIPPENAW NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 25 W 4 th Mer.

Meander Corner common to Sections

15, and 22

Corner consists of a 3<sup>rd</sup> class 3-sided iron pin

State condition GOOD

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

|      |  |      |  |
|------|--|------|--|
| S.22 |  | M.C. |  |
| M.C. |  | S.15 |  |

N W S E

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|  |  |  |  |

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

|      |      |  |  |
|------|------|--|--|
| M.C. | M.C. |  |  |
| S.22 | S.15 |  |  |

|      |      |  |  |
|------|------|--|--|
| B.T. | B.T. |  |  |
|------|------|--|--|

Species W. Birch W. Spruce

Diameter 6" 10"

Bearing N18°E S49°E

Distance 51 Lks 126 Lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Records show it was set by County Surveyor.

*Arthur J. Johnson*

(Signature)

1/31/40


(Date)

Squad Foreman

(Title)

N-15-16

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

CHIPPEWA NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 25 W 4th Mer.

Wander Corner common to Sections

15 and 22

Corner consists of a 3-sided post 3-sided iron pin place

State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

|       |       |  |  |
|-------|-------|--|--|
| S. 22 | M.C.  |  |  |
| M.C.  | S. 15 |  |  |

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|  |  |  |  |

N W S E NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

|               |               |  |  |
|---------------|---------------|--|--|
| M.C.<br>S. 22 | M.C.<br>S. 15 |  |  |
| B.T.          | B.T.          |  |  |

Species W. Birch W. Spruce

Diameter 6" 10"

Bearing N18° E S49° E

Distance 51 lks 126 lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? records show it was set by County Surveyor.

*Arthur J. Johnson*  
 (Signature)

Squad Foreman  
 (Title)

1/31/40  
 (Date)

NI-15-16

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57 N R. 25 W 4 th Mer.