

U. S. Department of Agriculture

FOREST SERVICE

N 16-17

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. **57 N** R. **25 W** 4th Mer.

Meander Corner common to Sections

....., **15**., and **22**.....

Corner consists of a **3rd described post** ~~(set)~~ in place

State condition **good**.....

Dimensions above ground **30**..... inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S. 15		S. 22	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. 15			
B.T.			

Species **Dry cedar**.....

Diameter **6"**.....

Bearing **N 75° E**.....

Distance **8 lks**.....

Do you believe this to be a genuine Land Office Corner? **No**

If not, why? **Reset by county from original**

B.T. which is the one still there......

Arthur J. Johnson
(Signature)

1/30/40
(Date)

Squad Foreman
(Title)

new trail to cabin.

This corner lies 4 chains west of

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57 N. R. 25 W. 4 1/2 Mer.

U. S. Department of Agriculture
FOREST SERVICE

N-16-17

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 25 W 4 Th Mer.

Meander Corner common to Sections

15, and 22

Corner consists of a 3*scribed post (iron) in place



State condition good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Dry Cedar

Diameter 6"

Bearing N75°E

Distance 8 Lks

Do you believe this to be a genuine Land Office Corner? NO
If not, why? Reset by county from original
B.T. which is the one still there.

Arthur J. Johnson
(Signature)

1/30/40
(Date)

Squad Foreman
(Title)

N-16-17

new trail to cabin.

This corner lies 4 chains west of

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 57 N R. 25 W 4 th Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

~~CHIPPEWA~~ NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 25 W 4th Mer.

~~Header~~ Corner common to Sections

15, and 22

Corner consists of a 3 inscribed post ~~(11)~~ in place

State condition good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>S. 15</u>		<u>S. 22</u>	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>S. 15</u>			
<u>B.T.</u>			

Species dry cedar

Diameter 6 in

Bearing N75°E

Distance 8 lks

Do you believe this to be a genuine Land Office Corner? no

If not, why? reset by county from original

B.T. which is the one still there.

Arthur J. Johnson
(Signature)

Squad Foreman
(Title)

1/30/40
(Date)

N-16-17

new trail to cabin.

This corner line & chains west of

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)