

U. S. Department of Agriculture
FOREST SERVICE

A-1
2725

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 & 58N. R. 26 & 27W. 4th P. Mer.

Township

Corner common to Sections

S. 1-58-27, 6-57-26, 31-58-26, and 36-58-27

Corner consists of a iron pipe & wood stake in place

State condition : good

Dimensions above ground pipe 3x6, stake 4x4x36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

T58N.	S	S. 6	S. 31
R27W.	1	T57N	T58N.
S36		R26W	R26W.

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T58N R27W S36			
BT			

Species R. Pine

Diameter 24"

Bearing N53° W.

Distance 1.12 ch.

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

Seth W. Peterson

(Signature)

Feb. 8, 1938

(Date)

Jr. Assist. to Tech.

(Title)

2-1

On west slope, near top of low ridge. Birch, aspen and brush.

Corner again.

Give any further facts which will aid in finding this


0.64 chains distant.

from which this Corner bears S. 45° E.

side of tree

tree 8 inches diameter, on the SK

Metal Location Poster is on aspen



(Make sketch of topography near Corner)