

U. S. Department of Agriculture
FOREST SERVICE

8-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

NC (#2) 1/16 Corner common to Sections

9, and

Corner consists of 3" spruce post (not) in place

State condition Iron rod Good

Dimensions above ground 30" post, red 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	#		5
	2		
	1/16		9

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S			
9			
BT			

Species Spruce

Diameter 5"

Bearing S 15° E

Distance 82.1 Ks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

KING
(Signature)


8/2/35
(Date)

(Title)

E-G-11

Corner again.
Corner of 25th and North

Give any further facts which will aid in finding this
821Ks: chains distant.
From which this Corner bears N 15° W
side of tree
tree 5 inches diameter, on the NW
Metal Location Poster is on a spruce



(Make sketch of topography near Corner)

T. 57N R. 26W 4th Mer.

U. S. Department of Agriculture

FOREST SERVICE

~~8-11~~

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

CN (# 2) 1/16 Corner common to Sections

9, and
Corner consists of ^{iron rod} spruce post (not) in place

State condition good

Dimensions above ground 30" post, 6" eye inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	#		S
	2		
	1/16		9

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S			
9			
BT			

Species Spruce

Diameter 5"

Bearing S 15° E

Distance 82 1/2

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

King
(Signature)

8/2/35
(Date)

(Title)

F.G. 11

Corner again.
Get this on N side of 76 swamp


Give any further facts which will aid in finding this
82 lks. - chains distant.

from which this Corner bears N 15° W

side of tree

tree 5" inches diameter, on the NW

Metal Location Poster is on a SP-100



(Make sketch of topography near Corner)

T. 57 N R. 26 W Mer. 44 E

U. S. Department of Agriculture

FOREST SERVICE

GA
F-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 R. 26 4 Mer.

1/16 # 5

Corner common to Sections

Section 9, and

Corner consists of a 4" spruce & 10" iron pipe (not) in place


State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Spruce

Diameter 4"

Bearing S 15° E

Distance 76 ch.

Do you believe this to be a genuine Land Office Corner? No.

If not, why? Corner located by

County survey.

(Signature)

(Date)

(Title)

F-11

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer.

7

R. 26

T. 57

U. S. Department of Agriculture
FOREST SERVICE

Shippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57 N. R. 26 W. 4th Mer.

1/16 #5 Corner common to Sections

and 9

Corner consists of a 4" Spruce + 12" Iron pipe (not) in place
State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Spruce

Diameter 4"

Bearing S 15° E

Distance 76.1ks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Corner located by

County Essex

Data taken from CCC survey notes by

P. B. Centerwall

(Signature)

7/15/37

(Date)

JUN. Forester

(Title)

11-7

No location poster Tacked
up yet.

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. 57 N. R. 26 W. 44 Mer.