

U. S. Department of Agriculture  
FOREST SERVICE

A-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 26W 4<sup>th</sup> Mer.

Section Corner common to Sections  
34, 33, 3, and 4

Corner consists of a 4" balsam post (~~was~~) in place  
State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S 33	S 4	S 3	S 34
---------	--------	--------	---------

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 33	S 4	S 3	S 34
			B.T.

Species \_\_\_\_\_ W. birch  
Diameter \_\_\_\_\_ 8"  
Bearing \_\_\_\_\_ N. 20° E.  
Distance \_\_\_\_\_ 58 links

Do you believe this to be a genuine Land Office Corner? yes

If not, why? Note. Found old gov. B.T. with scribing plainly visible and re-established temp post by referring to gov. field notes

Ernest Perry  
(Signature)


Field Ass't  
(Title)

10-3-34  
(Date)

A-13

Corner is located 10.95 chains South of spruce swamp  
brs E & W  
Corner again.

Give any further facts which will aid in finding this  
9 links ~~chains distant~~  
from which this Corner bears N4°E  
side of tree  
tree 2 inches diameter, on the N.E.  
Metal Location Poster is on a W. pine



(Make sketch of topography near Corner)

T. 58 N. R. 26 W. 4th Mer.

May  
Lake Camp  
copy

Form 374-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

A-13

CORNERS OF THE PUBLIC SURVEY



T. <sup>58</sup> 57 N., R. 26 W., 4<sup>th</sup> Mer.  
section Corner common to Sections  
3, 4, 33, and 34

Corner consists of a 4" Balsam stake (not) in place  
State condition Good

Dimensions above ground 30 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Blaze evident but scribing rotted



Blaze evident but scribing chopped off



Species Balsam fir Wh. Birch  
Diameter 7" 8"  
Bearing S 60° E N 54° E  
Distance 0.56 chs. 0.30 chs.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Former report by Ernest Perry stated that scribing on birch was plainly evident - has recently been chopped away. Located Balsam B.T. from D.L.O. notes.

Charles J. Knoblauch  
(Signature)  
Junior Forester  
(Title)

July 19, 1937  
(Date)


4-13

Corner is at intersection of original N 75, E 8 W  
loged line. A 9" white pine 4 1/2 in dia. S. of corner has  
large logs facing corner. A 10" wh. pine 3 in dia west  
of corner has old logs on W. side. Wh. spruce  
mentioned above has 2 old logs facing corner  
Balsam P. T. almost notted away - a fallen limb  
protected upper box.

Corner again. Other metal location poster is on  
dead 9" wh. pine from which this corner  
beard 5.6 W 4 1/2 in dia.  
Give any further facts which will aid in finding this  
chains distant.

0.25  
from which this Corner bears 5.50 W

side of tree  
tree 14 inches diameter, on the SW  
Metal Location Poster is on a white spruce



(Make sketch of topography near Corner)

Marcell  
R.S. copy

U. S. Department of Agriculture  
FOREST SERVICE

86-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. <sup>58</sup>57 N., R. 26 W., 4<sup>th</sup> Mer.

Section Corner common to Sections

3, 4, 33, and 34

Corner consists of a 4" Balsam stake (not) in place



State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<u>Glaze evident but scribing rotted</u>		<u>Glaze evident but scribing chopped out</u>

Species	<u>Balsam fir</u>	<u>W. Birch</u>
Diameter	<u>7"</u>	<u>8"</u>
Bearing	<u>S60°E</u>	<u>N54°E</u>
Distance	<u>0.56 chs.</u>	<u>0.30 chains</u>

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Former report by Ernest Perry stated that scribing on birch was plainly evident - has recently been chopped away. Located Balsam B.T. from Govt. notes.

Charles J. Knoblauch  
(Signature)  
Justin Forester  
(Title)

July 19, 1937  
(Date)


Give any further facts which will aid in finding this corner again. Other metal location poster is on dead 9" wh. pine from which this corner bears 5.6° W 72.2' S. 14 inches diameter, on the SW side of tree.

Corner is at intersection of original N 55° E 84 yds. along line. 9" white pine & line S. of corner had long logs facing corner, 10" wh. pine W. of corner & line had 2 logs on W. side, white spars mentioned above had 2 old logs facing corner, Balsam B.T. almost killed away - fallen Birch protected upper box.

21-A

from which this corner bears 5.50° W 0.25 chains distant.

Metal Location Poster is on a white spruce tree 14 inches diameter, on the SW side of tree.



(Make sketch of topography near Corner)

T. 58 N., R. 26 W., 4th Mer.