

U. S. Department of Agriculture
FOREST SERVICE

E-15

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

M.C. Corner common to Sections

3, and 10

Corner consists of a 14" N. pine Blazed on both sides (not) in place

State condition good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		S 10	
		BT	

Species _____ N. pine _____

Diameter _____ 14" _____

Bearing _____ S 31° W _____

Distance _____ 14 1/2' _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

E. M. Meyer

(Signature)

Field Ass't.

(Title)

1-5-34

(Date)

E-15

Corner again.
Land Rolling, second growth aspen and birch


Give any further facts which will aid in finding this
17 1/2' chains distant.

from which this Corner bears N 31° E

side of Tree

tree 14 inches diameter, on the N E

Metal Location Poster is on a N. pine



(Make sketch of topography near Corner)

T. 54 N. R. 26 W. 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST E15
CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

MC Corner common to Sections

.....,, 3, and 10
Corner consists of a 14" N. Pine Blazed ^{on both sides} ~~(not)~~ in place

State condition good

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		5 10	
		BT	

Species N. Pine

Diameter 14"

Bearing S 31° W

Distance 14 1/2'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

E. M. Meagher
(Signature)

1-5-34
(Date)

Field Ass't.
(Title)

Land rolling, second growth aspen and birch
Corner again.

Give any further facts which will aid in finding this


17 1/2 chains distant.

from which this Corner bears N 31° E

side of Tree

tree 14 inches diameter, on the N E

Metal Location Poster is on a N. Pine



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

E-15

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 57 N R. 26 W 4th Mer.

M.C. Corner common to Sections
3, and 10

Corner consists of a 14" N. pine Blazed (not) in place on both sides

State condition good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		S 10	
		BT	

Species _____ N. pine

Diameter _____ 14"

Bearing _____ S 31° W

Distance _____ 14 1/2'

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

Emin Meagher
(Signature)

1-5-34
(Date)

Field Assit.
(Title)

E-15

Land rolling, second growth aspen and birch

Corner again.

Give any further facts which will aid in finding this

17 1/2' glass distant.

from which this Corner bears

N. 31. E


side of Tree

tree 14 inches diameter, on the

N E

Metal Location Poster is on a

N. Pine



(Make sketch of topography near Corner)

T. 57 N R. 26 W 4th Mer.